



Changes for the Better

JY997D12501A

DATE : 11/2003

FX2C-I/O-CON, FX2C-I/O-CON-S, FX2C-I/O-CON-SA



Caution

The pin numbers or "▲" mark printed on this product does not correspond to the pin array of the connector on the connected equipment. It is necessary to perform wiring while referring to the manual of the connected equipment and according to the pin array of the connector on the connected equipment. Incorrect wiring may cause a fire, breakdown, or malfunction.

© 2003 MITSUBISHI ELECTRIC CORPORATION