

IB番号 IB No.	IB-0800475-F
形名 Model	AJ65ABTP3-16D-U

AJ65ABTP3-16D 形診断機能付き DC24V 入力ユニット (プラスコン (シンク) タイプ) ユーザーズマニュアル AJ65ABTP3-16D 24VDC Input Module With Diagnostic Functions (Positive Common/Sink Type) User's Manual

●安全上のご注意● (ご使用前に必ずお読みください)

本製品のご使用に際しては、本マニュアルをよくお読みいただくと共に、安全に対して十分に注意を払って、正しい取扱いをさせていただきようお願いいたします。

本マニュアルで示す注意事項は、本製品に関するもののみについて記載したもので、シーケンサシステムとしての安全上のご注意に関しては、使用するCPUユニットのユーザーズマニュアルを参照してください。

この「安全上のご注意」では、安全注意事項のランクを「△警告」、△注意」として区分してあります。

- △警告** 取扱いを誤った場合に、危険な状況が起こりえて、死亡または重傷を受ける可能性があります。
- △注意** 取扱いを誤った場合に、危険な状況が起こりえて、中程度の傷害や軽傷を受ける可能性が想定される場合および物的損害だけの発生が想定される場合。

なお、△注意に記載した事項でも、状況によっては重大な結果に結びつく可能性があります。

いずれも重要な内容を記載していますので必ず守ってください。本マニュアルは必要ときに読めるよう大切に保管すると共に、必ず最終ユーザまでお届けいただくようお願いいたします。

【設計上の注意事項】

△警告

- データリンクが交信異常になったとき、交信異常時は次のような状態になります。交信状態情報を使って、システムが安全側に働くようにシーケンサプログラム上でインターロック回路を構成してください。誤出力、誤動作により事故の恐れがあります。
- (1)リモートI/O局からの入力は、全点OFFします。
- (2)リモートI/O局からの出力は、全点OFFします。
- リモートI/Oユニットの故障によっては、出力がONの状態を保持したり、OFFの状態を保持することがあります。重大な事故につながるような出力信号については、外部で監視する回路を設けてください。
- リモート入出力信号の中で、「使用禁止」の信号はシステムで使用しているためユーザで使用しないでください。また、リモートレジスタの中で、「使用禁止」にデータを書き込まないでください。万一、「使用禁止」に対するデータの書き込みまたはユーザが「使用禁止」の信号を使用 (ON/OFF) された場合、ユニットとしての機能は保証できません。

△注意

- ユニットは、CPUユニットユーザーズマニュアル記載の一般仕様の環境で使用してください。範囲外の環境で使用すると、感電、火災、誤動作、製品の損傷、あるいは劣化の原因になります。
- 制御線や通信ケーブルは、主回路や動力線などと束ねたり、近接したりしないでください。100mm以上を目安として離してください。ノイズにより、誤動作の原因になります。

【取付け上の注意事項】

△注意

- ユニットの導電部分には直接触らないでください。ユニットの誤動作、故障の原因になります。
- ユニットは、DIN レールまたは取付けネジにて、確実に固定し、取付けネジは規定トルク範囲内で確実に締め付けてください。ネジの締め付けがゆるいと、落下、短絡、誤動作の原因になります。ネジを締め過ぎると、ネジやユニットの破損による落下、短絡、誤動作の原因になります。
- 各接続ケーブルのコネクタは装着部に確実に装着してください。接触不良により、誤動作の原因になります。

【配線上の注意事項】

△警告

- 配線作業は、必ずシステムで使用している外部供給電源を全相遮断してから行ってください。全相遮断しないと、感電またはユニットの故障や誤動作の原因になります。

△注意

- FG 端子は、シーケンサ専用の D 種接地 (第三種接地) 以上で必ず接地を行ってください。感電、誤動作の恐れがあります。
- 空き端子ネジは必ず締め付けトルク範囲 (0.42 ~ 0.50N・m) で締め付けてください。圧着端子と短絡する原因になります。
- 圧着端子は、適合圧着端子を使用し、規定のトルクで締め付けてください。先期形圧着端子を使用すると、端子ネジがゆるんだ場合に脱落し、故障の原因になります。
- ユニットへの配線は、製品の定格電圧および端子配列を確認した上で正しく行ってください。定格と異なる電圧の入力や、電源を接続、誤配線をする、火災、故障の原因になります。
- 端子ネジの締め付けは、規定トルク範囲で行ってください。ネジの締め付けがゆるいと、短絡、火災、誤動作の原因になります。ネジを締め過ぎると、ネジやユニットの破損による落下、短絡、火災、誤動作の原因になります。
- ユニット内に切粉や配線クズなどの異物が入らないように注意してください。火災、故障、誤動作の原因になります。

●SAFETY PRECAUTIONS● (Read these precautions before using this product.)

Before using this product, please read this manual carefully and pay full attention to safety to handle the product correctly.

The precautions given in this manual are concerned with this product only. For the safety precautions of the programmable controller system, refer to the user's manual for the CPU module used.

In this manual, the safety precautions are classified into two levels: "△WARNING" and "△CAUTION".

- △WARNING** Indicates that incorrect handling may cause hazardous conditions, resulting in death or severe injury.
- △CAUTION** Indicates that incorrect handling may cause hazardous conditions, resulting in minor or moderate injury or property damage.

Under some circumstances, failure to observe the precautions given under "△CAUTION" may lead to serious consequences. Observe the precautions of both levels because they are important for personal and system safety. Make sure that the end users read this manual and then keep the manual in a safe place for future reference.

【Design Precautions】

△WARNING

- In the case of a communication failure in the network, the status of the error station will be as follows:
 - All inputs from remote I/O stations are turned off.
 - All outputs from remote I/O stations are turned off.
 Check the communication status information and configure an interlock circuit in the sequence program to ensure that the entire system will operate safely. Incorrect output or malfunction due to a communication failure may result in an accident.
- Outputs may remain on or off due to a failure of a remote I/O module. Configure an external circuit for monitoring output signals that could cause a serious accident.
- Do not use any "use prohibited" signals as a remote input or output signal. These signals are reserved for system use. Also do not write any data to the "use prohibited" of the remote register. If such operations are performed, correct operation of the module cannot be guaranteed.

△CAUTION

- Use the module in an environment that meets the general specifications in the user's manual for the CPU module used. Failure to do so may result in electric shock, fire, malfunction, or damage to or deterioration of the product.
- Do not install the control lines or communication cables together with the main circuit lines or power cables. Keep a distance of 100mm or more between them. Failure to do so may result in malfunction due to noise.

【Installation Precautions】

△CAUTION

- Do not directly touch any conductive parts of the module. Doing so can cause malfunction or failure of the module.
- Securely fix the module with a DIN rail or mounting screws. Tighten the screws within the specified torque range. Undertightening can cause drop of the screw, short circuit or malfunction. Overtightening can damage the screw and/or module, resulting in drop, short circuit, or malfunction.
- Securely connect the cable connectors. Poor contact may cause malfunction.

【Wiring Precautions】

△WARNING

- Shut off the external power supply (all phases) used in the system before wiring. Failure to do so may result in electric shock or cause the module to fail or malfunction.

△CAUTION

- Individually ground the FG terminal of the programmable controller with a ground resistance of 100Ω or less. Failure to do so may result in electric shock or malfunction.
- Tighten any unused terminal screws within the specified torque range (0.42 to 0.50N-m). Failure to do so may cause a short circuit due to contact with a solderless terminal.
- Use applicable solderless terminals and tighten them within the specified torque range. If any spade solderless terminal is used, it may be disconnected when the terminal screw comes loose, resulting in failure.
- Check the rated voltage and terminal layout before wiring to the module, and connect the cables correctly. Connecting a power supply with a different voltage rating or incorrect wiring may cause a fire or failure.
- Tighten the terminal screw within the specified torque range. Undertightening can cause short circuit, fire, or malfunction. Overtightening can damage the screw and/or module, resulting in drop, short circuit, fire, or malfunction.
- Prevent foreign matter such as dust or wire chips from entering the module. Such foreign matter can cause a fire, failure, or malfunction.

△注意

- ユニットに接続する電線やケーブルは、必ずダクトに納めるか、またはクランプによる固定処理を行ってください。ケーブルをダクトに納めなかったり、クランプによる固定処理をしないで、ケーブルのふらつきや移動、不注意の引っ張りなどによるユニットやケーブルの破損、ケーブルの接続不良による誤動作の原因となります。
- 電源・FG用ワンタッチコネクタの空きには、必ず無配線のワンタッチコネクタプラグを装着するようにしてください。故障、誤動作の原因となります。
- 制御線と通信ケーブルは束ねたり、近接したりしないでください。ノイズにより、誤動作の原因になります。
- ユニットに接続された通信ケーブルや電源ケーブルを取りはずすときは、ケーブル部分を手に持たず、ユニットに接続している部分のコネクタを手で取りはずしてください。コネクタなしのケーブルは、ユニットに接続している部分のネジをゆるめてから取りはずしてください。ユニットに接続された状態でケーブルを引っ張ると、ケーブルやケーブルのコネクタの破損、ケーブルの接続不良による誤動作の原因となります。
- 外部接続機器の異常やシーケンサの故障などによる過電流が長時間継続して流れた場合、発煙、発火の恐れがありますので、外部にヒューズなどの安全回路を設けてください。
- 短絡が発生したときは、速やかに原因を取り除いてください。短絡状態のまま放置すると、内部温度が上昇し、誤動作、故障の原因となります。

【立上げ・保守時の注意事項】

△警告

- 導電中に端子やコネクタに触れないでください。感電の原因になります。
- 清掃、端子ネジ、ユニット取付けネジの増し締めは、必ずシステムで使用している外部供給電源を全相遮断してから行ってください。全相遮断しないと、ユニットの故障や誤動作の原因になります。

△注意

- ユニットの分解、改造はしないでください。故障、誤動作、ケガ、火災の原因になります。
- ユニット背面のネジをゆるめたり、締め付けたりしないでください。ユニットが分解、故障し、誤動作、ケガ、火災の原因になります。
- ユニットは落下させたり、強い衝撃を与えないでください。ユニットの破損の原因になります。
- ユニットの取付け、取りはずしは、必ずシステムで使用している外部供給電源を全相遮断してから行ってください。全相遮断しないと、ユニットの故障や誤動作の原因になります。
- 端子部の着脱は、製品ご用意後、50回以内としてください。(JIS B 3502に準拠)
- ユニットに触れる前には、必ず接地された金属などに触れて、人体などに帯電している静電気を放電してください。静電気を放電しないと、ユニットの故障や誤動作の原因になります。

【廃棄時の注意事項】

△注意

- 製品を廃棄するときは、産業廃棄物として扱ってください。

●製品の適用について●

- 当社シーケンサをご使用いただくにあたりましては、万一シーケンサに故障・不具合などが発生した場合でも重大な事故にいたらないよう用途であること、および故障・不具合発生時にはバックアップやフェールセーフ機能が機器外部でシステムの実施されていることをご使用の条件とさせていただきます。
- 当社シーケンサは、一般工業などへの実用を対象とした汎用品として設計・製作されています。したがって、以下のような機器・システムなどの特殊用途へのご使用については、当社シーケンサの適用を除外させていただきます。万一使用された場合は当社として当社シーケンサの品質、性能、安全に関する一切の責任 (債務不履行責任、瑕疵担保責任、品質保証責任、不法行為責任、製造物責任を含むがそれらに限定されない) を負わないものとさせていただきます。
 - 各電力会社等の原子力発電所およびその他発電所向けなどの公共への影響が大きい用途
 - 鉄道各社および官公庁様など、特別な品質保証体制の構築を当社にご要求する用途
 - 航空宇宙、医療、鉄道、燃焼・燃料装置、乗用移動体、有人搬送装置、娯楽機械、安全機械など・生命、身体、財産に大きな影響が予測される用途

ただし、上記の用途であっても、具体的に使途を限定すること、特別な品質 (一般仕様を超えた品質等) をご要求されないこと等を条件に、当社判断にて当社シーケンサの適用可否となる場合もございますので、詳細につきましては当社窓口へご相談ください。

●安全注意事項● (使用之前请务必阅读)

在使用本产品之前，应仔细阅读本手册，同时在充分注意安全的前提下正确操作。本手册中仅记载与本产品有关的注意事项。关于可编程控制器系统方面的安全注意事项，请参阅所使用的CPU模块的用户手册。

在“安全注意事项”中，安全注意事项被分为“△警告”和“△注意”两个等级。

- △警告 表示操作错误时，可能会引起危险，导致死亡或重伤事故。
- △注意 表示操作错误时，可能会引起危险，导致中度伤害或轻伤，或导致财物损失。

此外，根据情况不同，即使标注为“△注意”的事项也有可能引发严重后果。这两个等级的注意事项记载的均为重要内容，请务必遵守。

请妥善保管本手册以备需要时查阅，并将本手册交给最终用户。

【设计注意事项】

△警告

- 数据链接出现通信异常时，通信异常站会变为以下状态。应使用通信状态信息，在顺控程序上配置互锁电路，以保证系统能安全运行。否则可能由于误输出、误动作而导致事故发生。
 - 来自远程I/O站的输入为全点OFF。
 - 来自远程I/O站的输出为全点OFF。
- 远程I/O模块的故障可能会导致输出保持ON状态或OFF状态。对于可能发生重大事故发生的输出信号，应在外部设置置位电路。
- 远程输入输出信号中，由于“禁止使用”的信号为系统所使用，因此用户请勿使用。请勿向远程寄存器的“禁止使用”中写入数据。如果向“禁止使用”中进行数据写入或由用户使用“禁止使用”的信号 (使之ON/OFF)，将无法保证模块的功能。

△注意

- 应在CPU模块用户手册记载的一般规格环境下使用模块。如果在一般规格范围以外的环境中使用模块，可能导致触电、火灾、误动作、产品损坏或性能劣化。
- 请勿将控制线及通信电缆与主电路及动力线等捆扎在一起或相互靠得太近。应相距大约100mm以上距离。因为噪声有可能导致误动作。

【安装注意事项】

△注意

- 请勿直接触摸模块的导电部分。否则可能导致触电、故障。
- 模块应通过DIN导轨或者安装螺栓切实地加以固定，安装螺栓应在规定的扭矩范围内切实地拧紧。如果螺栓拧得过松，有可能导致掉落、短路或误动作。如果螺栓拧得过紧，有可能造成螺栓及模块破从而造成掉落、短路或误动作。
- 各连接电缆的连接，应切实安装在安装部。因为接触不良有可能导致误动作。

【配线注意事项】

△注意

- 请勿将控制线及通信电缆捆扎在一起或相互靠得太近。因为噪声有可能导致误动作。
- 在拆卸与模块相连接的通信电缆及电源电缆时，请勿用手拉扯电缆部分。带电口的电缆应握住与模块相连接部分的接口进行拆卸。不带接口的电缆应在松开与模块连接部分的螺栓后再进行拆卸。如果在与模块相连接的状态下拉扯电缆，可能导致模块及电缆损坏、电缆接触不良而导致误动作。
- 外部连接设备的异常及可编程控制器的故障等导致长时间过电流时，可能会导致冒烟、火灾，因此请在外部设置置位保险丝等安全电路。
- 如果一直处在短路状态，内部温度会上升，有可能导致故障、误动作。发生短路时，应立即排除短路原因。

【启动/维护注意事项】

△警告

- 在通电状态下请勿触摸端子或接口。否则可能导致触电。
- 在清洁模块或重新紧固端子螺栓、模块安装螺栓时，必须将系统使用的外部供电电源全部断开后再进行操作。如果未全部断开，有可能导致模块故障或误动作。

△注意


- 请勿拆解或改造模块。否则可能导致重大事故、误动作、人身伤害或火灾。
- 请勿拧松或拧紧模块背面的螺栓。否则可能造成模块分解、故障、导致误动作、人身伤害或火灾。
- 请勿使模块掉落或受到强烈冲击。否则可能导致模块破。
- 在拆装模块之前，必须将系统使用的外部供电电源全部断开后再进行操作。如果未全部断开，有可能导致模块故障或误动作。
- 产品投入使用后，端子排的拆装次数不应超过50次。(根据IEC61131-2规范)
- 在触摸模块之前，必须先触碰到已接地的金属等，释放掉人体所携带的静电。如果不释放掉静电，有可能导致模块故障或误动作。

【报废处理注意事项】

△注意

- 本产品报废时，应当作为工业废物处理。

改正中国 RoHS による電器電子製品中の有害物質使用制限表示 「电器电子产品有害物质限制使用标识要求」の表示方式



含有有害6物質の名称、含有量、含有部品
 本製品中所含の有害6物質の名称、含有量、含有部品如下表所示。

製品中有毒物質の名称及含量

部材名称	有害物質	鉛 (Pb)	汞 (Hg)	銅 (Cu)	六价鉻 (Cr(VI))	多環芳香 (PBB)	多環二苯醚 (PBDE)
印刷基板	×	○	○	○	○	○	○
外装	○	○	○	○	○	○	○

本表格依SJ/T 11364 的规定编制。
 ○表示该有害物质在该部件所有均质材料中的含量均在GB/T 26572 规定的限量要求以下。
 ×表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T 26572 规定的限量要求。

【配线注意事項】

△警告

- 在配線作业时，必須將系統使用的外部供電電源全部斷開后再進行操作。如果未全部斷開，有可能導致触电或模块故障、誤動作。

△注意

- 必須將FG端子与可編程控制器的專用接地線連接。否則有可能導致触电、誤動作。
- 空開端子螺栓必須在拧紧扭矩範圍 (0.42~0.50N・m) 內拧紧。否則可能與壓裝端子發生短路。
- 應使用合適的壓裝端子，并按規定扭矩拧紧。如果使用Y型壓裝端子，端子螺栓松動時可能導致脫落或故障。
- 進行模块配線作业时，应在确认产品的额定电压及端子排列的基础上正确进行配线操作。如果输入了与额定值不符的电压、连接了与额定值不符的电源或配线错误，可能导致火灾或故障。
- 应在规定的扭矩范围内拧紧端子螺栓。如果螺栓拧得过松，有可能导致短路、火灾或误动作。如果螺栓拧得过紧，有可能造成螺栓及模块破从而造成掉落、短路、火灾或误动作。
- 应注意防止切屑及配线头等异物掉入模块内。否则有可能导致火灾、故障或误动作。
- 与模块相连接的电线及电缆必须收入套管中，或者用夹具进行固定处理。如果未将电缆收入套管或未用夹具进行固定处理，可能由于电缆的晃动及移动、不稳定的操作而造成模块及电缆破、电接触不良而导致误动作。
- 空因的电源、FG用快速接口上必須安裝無配線的快速接口插頭。否則可能導致故障、誤動作。

1. 仕様

項目	内容
CC-Link Ver.	CC-Link Ver.1.10
CC-Link 局種	リモートデバイス局
入力点数	16点
絶縁方式	フォトカプラ絶縁
定格入力電圧	DC24V (リップル率5%以内)
使用電圧範囲	DC20.4V ~ DC28.8V
最大同時入力点数	100%同時ON
ON電圧/ON電流	14V以上 / 3.5mA以上
OFF電圧/OFF電流	6V以下 / 1.7mA以下
入力抵抗	約3.8kΩ
応答時間	OFF→ON 1.5ms以下 (DC24V時) ON→OFF 1.5ms以下 (DC24V時)
コモン方式	16点1コモン (スプリングクランプ端子台プッシュインタイプ3線式)
入力形式	プラスコン (シンクタイプ)
占有高さ	1局32点割付 (16点使用)
入力部内部回路用電源電流	電圧 DC24V (リップル率5%以内) (許容電圧範囲 DC20.4 ~ DC28.8V) 電流 30mA以下 (DC24V, 全点ON時) 外部負荷電流は含まず
I/O電源電流	8A以下/コモン*
短絡 (地絡) 検出電流	50mA / 1点以上
断線 (未接続) 検出電流	0.3mA / 1点以下
ユニット電圧	DC24V (リップル率5%以内) (許容電圧範囲 DC20.4 ~ DC26.4V) 電流 55mA以下 (DC24V, 全点ON時)
ノイズ耐量	DCタイプのノイズ電圧 500Vp-p, ノイズ幅 1μs, ノイズ周波数 25 ~ 60Hzのノイズシミュレータによる
絶電圧	DC 外部端子一括—アース間 AC500V 1分間
耐振抵抗	DC 外部端子一括—アース間 DC500V 絶縁抵抗計にて10MΩ以上
保護等級	IP1XB
外形寸法	50(H) × 145(W) × 57.5(D)mm
質量	0.31kg
通信部	通信用ワンタッチコネクタ (伝送回路) (6ピン) 圧接タイプ・コネクタ用プラグは別売: A6CON-LJ5P コネクタ用プラグは別売: A6CON-LJ5P コネクタ用プラグは別売: A6CON-LJ5P 通信用オンラインコネクタ: A6CON-LJ5P
電源部	電源・FG用ワンタッチコネクタ [ユニット電源・FG] (6ピン) 圧接タイプ・コネクタ用タイプは別売: A6CON-PW5P, A6CON-PW5P-S0D コネクタ用プラグは別売: A6CON-PW5P 電源用オンラインコネクタ: A6CON-PWJ5P
入力部	2ピース スプリングクランプ端子台プッシュインタイプ [入出力電源、I/O信号]
ユニット取付けネジ	D2-M4ネジ (締付トルク範囲: 0.82 ~ 1.11N・m) DINレールでの取付け可能、6方向取付け可
適用DINレール	TH35-7.5Fe, TH35-7.5Al (JIS C 2812に準拠)
通信ケーブル	通信ケーブル: FANUC-110SBH, GS-110 0.66 ~ 0.98mm ² (AWG18) [φ2.2 ~ 2.3mm (A6CON-PW5P)] 電源・FG用コネクタ [φ2.0 ~ 2.3mm (A6CON-PW5P-S0D)] 素線径 0.16mm以上 絶縁被覆材質 PVC (耐熱ビニル) 最大定格電流: 7A *
入力用スプリングクランプ端子台	より線径 0.08 ~ 1.5mm ² (AWG28 ~ 16) * 3
適合電線サイズ	• TE 0.5-8, TE0.5-10 (株式会社ニチフ端子工業) [適合電線サイズ: 0.5mm ²] • TE 0.75-8, TE 0.75-10 (株式会社ニチフ端子工業) [適合電線サイズ: 0.75mm ²] • TE 1.0-8, TE 1.0-10 (株式会社ニチフ端子工業) [適合電線サイズ: 0.9 ~ 1.0mm ²] • TE 1.5-8, TE 1.5-10 (株式会社ニチフ端子工業) [適合電線サイズ: 1.25 ~ 1.5mm ²] • FA-VTC0125T9 (三菱電機エンジニアリング株式会社) [適合電線サイズ: 0.3 ~ 1.65mm ²] • FA-VTCW125T9 (三菱電機エンジニアリング株式会社) [適合電線サイズ: 0.3 ~ 1.65mm ²] • AI 0.25-12BU (フエニックス・コンタクト株式会社) [適合電線サイズ: 0.25mm ²] • AI 0.34-8YT, AI 0.34-12TQ (フエニックス・コンタクト株式会社) [適合電線サイズ: 0.34mm ²] • AI 0.5-8WH, AI 0.5-10WH (フエニックス・コンタクト株式会社) [適合電線サイズ: 0.5mm ²] • AI 0.75-8GY, AI 0.75-10GY (フエニックス・コンタクト株式会社) [適合電線サイズ: 0.75mm ²] • AI 1-8RD, AI 1-10RD (フエニックス・コンタクト株式会社) [適合電線サイズ: 1.0mm ²] • AI 1.5-8BK, AI 1.5-10BK (フエニックス・コンタクト株式会社) [適合電線サイズ: 1.5mm ²]
適合圧着端子	

△CAUTION

- Place the cables in a duct or clamp them. If not, dangling cable may swing or inadvertently be pulled, resulting in damage to the module or cables or malfunction due to poor contact.
- Attach an unwired connector plug to an unused one-touch connector for power supply and FG. Failure to do so may cause failure or malfunction.
- Do not install the control lines together with the communication cables, or bring them close to each other. Failure to do so may cause malfunctions due to noise.
- Do not pull the cable part by hand when removing a communication cable and power supply cable from a module. For a cable with connector, remove it while holding the connector by hand. For a cable with no connector, loosen the screw securing the cable to the module and then remove it. Pulling a cable with connector to the module may damage the module or cable, or result in malfunction due to cable poor connection.
- When an overcurrent caused by an error of an external device or a failure of the programmable controller flows for a long time, it may cause smoke and fire. To prevent this, configure an external safety circuit, such as a fuse.
- If a short-circuit occurs, remove the cause immediately. If the short-circuit remains, the internal temperature of the module rises, resulting in malfunction or failure.

【Startup and Maintenance Precautions】

△WARNING

- Do not touch any terminal or connector while power is on. Doing so will cause electric shock.
- Shut off the external power supply (all phases) used in the system before cleaning the module or retightening the terminal screws or module mounting screws. Failure to do so may cause the module to fail or malfunction.

△CAUTION

- Do not disassemble or modify the modules. Doing so may cause failure, malfunction, injury, or a fire.
- Do not loosen or tighten the screws on the back of the module. Doing so may disassemble the module and cause failure, resulting in malfunction, injury, or a fire.
- Do not drop or apply strong shock to the module. Doing so may damage the module.
- Shut off the external power supply (all phases) used in the system before mounting or removing a module. Failure to do so may cause the module to fail or malfunction.
- After the first use of the product, do not mount/remove the terminal block to/from the module more than 50 times (IEC 61131-2 compliant).
- Before handling the module, touch a grounded metal object to discharge the static electricity from the human body. Failure to do so may cause the module to fail or malfunction.

【Disposal Precautions】

△CAUTION

- When disposing of this product, treat it as industrial waste.

●CONDITIONS OF USE FOR THE PRODUCT●


- Mitsubishi programmable controller (the PRODUCT) shall be used in conditions:
 - where any problem, fault or failure occurring in the PRODUCT, if any, shall not lead to any major or serious accident; and
 - where the backup and fail-safe function are systematically or automatically provided outside of the PRODUCT for the case of any problem, fault or failure occurring in the PRODUCT.
 - The PRODUCT has been designed and manufactured for the purpose of being used in general industries. MITSUBISHI SHALL HAVE NO RESPONSIBILITY OR LIABILITY (INCLUDING, BUT NOT LIMITED TO ANY AND ALL RESPONSIBILITY OR LIABILITY BASED ON CONTRACT, WARRANTY, TORT, PRODUCT LIABILITY) FOR ANY INJURY OR DEATH TO PERSONS OR LOSS OR DAMAGE TO PROPERTY CAUSED BY THE PRODUCT THAT ARE OPERATED OR USED IN APPLICATION NOT INTENDED OR EXCLUDED BY INSTRUCTIONS, PRECAUTIONS, OR WARNING CONTAINED IN MITSUBISHI'S USER INSTRUCTION AND/OR SAFETY MANUALS, TECHNICAL BULLETINS AND GUIDELINES FOR THE PRODUCT. ("Prohibited Application") Prohibited Applications include, but not limited to, the use of the PRODUCT in:
 - Nuclear Power Plants and any other power plants operated by Power companies, and/or any other cases in which the public could be affected if any problem or fault occurs in the PRODUCT.
 - Railway companies or Public service purposes, and/or any other cases in which establishment of a special quality assurance system is required by the Purchaser or End User.
 - Aircraft or Aerospace, Medical applications, Train equipment, transport equipment such as Elevator and Escalator, Incineration and Fuel devices, Vehicles, Manned transportation, Equipment for Recreation and Amusement, and Safety devices, handling of Nuclear or Hazardous Materials or Chemicals, Mining and Drilling, and/or other applications where there is a significant risk of injury to the public or property.
- Notwithstanding the above, restrictions Mitsubishi may in its sole discretion, authorize use of the PRODUCT in one or more of the Prohibited Applications, provided that the usage of the PRODUCT is limited only for the specific applications agreed to by Mitsubishi and provided further that no special

- * 1 渡り配線によって、複数ユニットに電源を供給した場合の消費電流の計算方法は、診断機能付き CC-Link リモート I/O ユニット ユーザーズマニュアルを参照してください。
- * 2 接続するケーブルの許容電流値以内で使用してください。
- * 3 スプリングクランプ端子台の電線挿入口に、電線を 2 本差し込む場合は、FA-VTCW125T9 (三菱電機エンジニアリング株式会社製) を使用してください。FA-VTCW125T9 を使用せずに、2 本以上の電線を差し込んだ場合、接触不良となる可能性があります。
- * 4 1 端子に 2 本の電線を差し込む場合に使用します。

- * 1 When supply the power to multiple modules in a transition wiring system, calculate the current consumption by referring to the CC-Link Remote I/O Module (With Diagnostic Functions) User's Manual.
- * 2 Use it within the allowable range of current for the cable to be connected.
- * 3 Insert only one wire into the pin of the spring clamp terminal block. Inserting two or more wires may result in a poor contact to the terminal.

2. 各部の名称と設定

2. Part Names and Settings



番号	名称	内容	
1)	運転状態表示用 LED	<p>PW LED 緑 ユニットの電源状態を示します。点灯: 電源 ON 時 消灯: 電源断時</p> <p>RUN LED 緑 リモート I/O ユニットの運転状態を示します。点灯: 正常運転 消灯: ウォッチドッグタイマーエラーが発生しています</p> <p>L RUN LED 緑 リモート I/O ユニットのマスターユニットとのデータ通信状態を示します。点灯: 通信正常時 消灯: 通信断時 (タイムオーバーエラー)</p> <p>L ERR LED 赤 リモート I/O ユニットのマスターユニットとのデータ通信異常状態を示します。点灯: 異常発生時 消灯: 異常解消時</p> <p>I/O PW LED 緑 外部供給電源の電源供給状態を示します。点灯: 外部供給電源 ON 時 消灯: 外部供給電源 OFF</p> <p>X0 ~ XF 緑 2 入力 ON/OFF 状態を示します。消灯: 入力 OFF</p> <p>赤 3 入力断線、未接続、短絡、または地絡状態を示します。点灯: 断線が発生中、または未接続*4 点灯: 短絡、または地絡が発生中*4</p>	
	2)	局番設定スイッチ	局番を指定するロータリスイッチです。1~64以外の値を設定するとエラーとなり、「L ERR」LED が点灯します。局番を重複して使用することはできません。*10は、局番の 10 の位を設定します。*11は、局番の 1 の位を設定します。
	3)	通信用ワンタッチコネクタ	通信ラインの接続用ワンタッチコネクタです。CC-Link システムの終端のユニットとなる場合は、終端抵抗付きワンタッチコネクタプラグ A6CON-TR11(N) を取り付けてください。
	4)	電源・FG 用ワンタッチコネクタ	ユニット電源ライン、または FG の接続用ワンタッチコネクタです。
	5)	スプリングクランプ端子台	入力信号用 2 ピースのスプリングクランプ端子台ブッシュインタイプです。
6)	電線挿入口	棒型端子をそのまま差し込みだけで接続できます。専用工具は不要です。市販工具にて開閉ボタンを押すことで抜き可能です。	
7)	開閉ボタン	アスタによる配線チェックが可能です。(適用メタチェックピン寸法: φ2mm の鋭角)	
8)	溝通チェック穴	端子台をユニットに固定するネジです。M3 ネジ (締付けトルク範囲: 0.42 ~ 0.57N・m)	
9)	2 ピース端子台固定ネジ	ユニットを強固に取り付ける場合にユニットに装着して使用します。ネジ取付け用固定具は、取りはずすことが可能です。	
10)	ネジ取付け用固定具 (付属品)	M4 ネジ (締付けトルク範囲: 0.82 ~ 1.11N・m)	
11)	DIN レール用フック	DIN レールにユニットを取り付けるためのフックです。	

- * 1 通信状態が解列中に局番設定スイッチを変更した場合は、不定期間隔で点滅します。
- * 2 断線 (未接続)、短絡 (地絡) が発生している場合は異常表示 (赤色) が優先され、入力状態を示す緑色 LED は点灯しません。
- * 3 断線 (未接続)、短絡 (地絡) が発生している間のみ、点滅/点灯します。継続して表示させるためには、断線表示指令 (RWwm + 2_H)、短絡表示指令 (RWwm + 3_H) を設定してください。
- * 4 断線表示指令 (RWwm + 2_H) を一定間隔で点滅させる (1) に設定している状態で、短絡表示指令 (RWwm + 3_H) を点灯させる (1) に設定している場合は、短絡表示指令 (RWwm + 3_H) が優先されます。(LED は赤点灯します)

3. 同梱品の確認

品名	個数
ユニット本体	1
AJ65ABTP3-16D 形診断機能付き DC24V 入力ユニット (プラスコモン (シンク) タイプ) ユーザーズマニュアル (本資料)	1
ネジ取付け用固定具	2

4. 使用周囲温度

本製品は、0 ~ 55 °C の範囲でご使用ください。

No.	Item	Description	
1)	PW LED	Green Indicates the power supply status of the module. ON: Power being supplied OFF: No power supplied	
	RUN LED	Green Indicates the operating status of the remote I/O module. ON: Normal operation OFF: A watchdog timer error occurs.	
	L RUN LED	Green Indicates the status of data communication between the remote I/O module and the master module. ON: Normal communication OFF: No communication (timeout error)	
	L ERR LED	Red Indicates the status of data communication error between the remote I/O module and the master module. ON: The station number is set outside the range. Flashing irregularly: The station number is changed during the operation.*1 Flashing irregularly: A terminating resistor is not installed. The module or CC-Link dedicated cable is affected by noise. OFF: Normal communication	
	I/O PW LED	Green Indicates the status of the external power supply. ON: Supplying power OFF: Not supplying power	
	X0 to XF	Green Indicates the ON/OFF status of input. ON: Input ON OFF: Input OFF	
	X0 to XF	Red*3 Indicates the disconnection, no connection, short-circuit, or ground fault of the input. Flashing: Disconnection or no connection occurs.*4 ON: A short-circuit or a ground fault occurs.*4	
	2)	Station number setting switch	A rotary switch to set a station number. If a number other than 1 to 64 is set, an error occurs and "L ERR" LED turns on. Note that a unique station number should be set. * Set the tens place of the number to x10. * Set the ones place of the number to x1
	3)	One-touch connector for communication	One-touch connector for communication line. When using the module at the end of the CC-Link system, attach the one-touch connector plug with terminating resistor (A6CON-TR11(N)) to the module.
	4)	One-touch connector for power supply and FG	One-touch connector for module power supply line and FG
5)	Spring clamp terminal block (push-in type)	2-piece spring clamp terminal block (push-in type) for input signals	
6)	Pin	A bar solderless terminal is connected by inserting it into the pin.	
7)	Open/close button	A cable or a terminal can be pulled out by pressing this button using a commercially available tool. (A dedicated tool is not required.)	
8)	Conduction check hole	The connection of a wire can be checked by inserting a tester in this hole. (Applicable check pin size of the tester: φ2mm, sharp angle)	
9)	2-piece terminal block fixing screw	Used to fix the terminal block to a module. M3 screw (tightening torque range: 0.42 to 0.57N·m)	
10)	Mounting bracket (accessory)	Used to install the module to a control panel. The bracket can be removed. M4 screw (tightening torque range: 0.82 to 1.11N·m)	
11)	DIN rail hook	Used to mount the module to a DIN rail.	


- * 1 If the station number is changed while communication is disconnected, the LED starts flashing irregularly.
- * 2 If the disconnection (no connection) or the short-circuit (ground fault) occurs, the red LED (indication of abnormal status) preferentially turns on. Therefore, the green LED (indication of ON/OFF status of input) does not turn on.
- * 3 The red LED is flashing/on during the occurrence of the disconnection (no connection) or the short-circuit (ground fault). To keep the LED flashing/on, set the disconnection indication command (RWwm + 2_H) and the short-circuit indication command (RWwm + 3_H).
- * 4 If "Turn on the LED (1)" is set to the short-circuit indication command (RWwm + 3_H) while "Flash the LED regularly (1)" is set to the disconnection indication command (RWwm + 2_H), the short-circuit indication command (RWwm + 3_H) is prioritized and the red LED turns on.

3. Packing list

Item	Quantity
Module	1
AJ65ABTP3-16D 24VDC Input Module With Diagnostic Functions (Positive Common/Sink Type) User's Manual (this document)	1
Mounting bracket	2

4. Operating Ambient Temperature

Use the module in the ambient temperatures of 0 to 55°C.



- * 1 スプリングクランプ端子台の電線挿入口に、電線を 2 本差し込む場合は、FA-VTCW125T9 (三菱電機エンジニアリング株式会社製) を使用してください。FA-VTCW125T9 を使用せずに、2 本以上の電線を差し込んだ場合、接触不良となる可能性があります。Insert only one wire into the pin of the spring clamp terminal block. Inserting two or more wires may result in a poor contact to the terminal.
- * 2 電源・FG 用ワンタッチコネクタの端子には、必ず無配線のワンタッチコネクタプラグを装着してください。Attach an unwired connector plug to an unused one-touch connector for power supply and FG.
- * 3 入力用スプリングクランプ端子台の 1A, 1C ピンは I/O 電源供給用として、18A, 18C ピンは I/O 電源の渡り配線用としてご使用ください。For I/O power supply, use 1A and 1C pins of a spring clamp terminal block for input. For transition wiring of I/O power supply, use the 18A and 18C pins.